



SERVICEINFO

AIC Germany
Automotive Components

STEERING KNUCKLE

AIC article no.: 59437 + 59438 / OE reference no.: 1 474 291 + 1 474 288



AIC article no.: 59437 | OE reference no.: 1 474 291



AIC article no.: 59438 | OE reference no.: 1 474 288



SERVICE NOTE!

Before installation, the 3 threads (see markings) for attaching the shielding plates must be drilled, as these are not present.

Accidents with effects on the axle geometry and thus a limited steering stability as well as changed grip of the tyres cannot be seen with the naked eye. Among the vehicle parts that are particularly affected by this are steering knuckles, which can warp. Such dama-

ge is particularly possible in the event of accidents and sometimes even unfortunate encounters of the vehicle, for example with high kerbs or potholes. As a consequence, the axle geometry must be checked and, if necessary, axle parts replaced.



ABNORMALITIES ON THE VEHICLE

- Limited steering stability
- Changed grip of the tyres



CAUSE

- Collision with another vehicle
- Driving over potholes
- Driving against kerbs



INSTALLATION NOTE

- Never heat the stub axle parts to loosen stuck screws. This will change the metal structure of the stub axle!
- Always check the axle geometry when replacing the stub axle and correct it if necessary.
- Check with a test drive the correct alignment of the steering wheel, as well as the steering behaviour.