



TB1069

LuK Service Info

Part Nr. 500 0076 11


Manufacturer: EICHER, HURLIMANN, JOHN DEERE, LAMBORGHINI, MASSEY FERGUSON, SDF

Art.-Nr.: 500 0076 11

500 0076 11 replaces / ersetzt / remplace / sustituye a / sostituisce 500 0139 20.



500 0139 20



500 0076 11

Call : +44 (0) 1432 264264
vehiclelifetimesolutions.schaeffler.com

SCHAEFFLER
REP>XPERT