





<b>HAZET</b> No.	 M	 Ø mm	$f$ mm	□ $V$ max	$l_1$ mm
<b>840-1</b>	M4	2	7	2.70	52.00
<b>840-2</b>	M6 - M7	3-3.5	10	3.80	58.50

<b>HAZET</b> No.	 M	 Ø mm	$f$ mm	□ $V$ max	$l_1$ mm
<b>840-3</b>	M8 - M10	4-4.5	13	4.90	66.00
<b>840-4</b>	M12 - M14	6-7	6	7.00	73.50
<b>840-5</b>	M14 - M18	8-9	21	9.00	81.50
<b>840-6</b>	M18 - M24	12		12.00	91.00
<b>840-7</b>	M24 - M33	15-16		14.50	105.50
<b>840-8</b>	M33 - M45	20		18.00	111.50