



TB1452

# LuK Service Info Part Nr. 500 0287 40

Manufacturer: DEUTZ FAHR / FENDT  
Art.-Nr.: 500 0287 40

Info: 500 0287 40 replaces / ersetzt / rem-  
place / sustituye a / sostituisce 500 0287 00

Product Improvement / Produktverbesserung / Amélioration du produit / de mejora de productos  
/ miglioramento del prodotto



500 0287 40  
OE 01266401

Call : +44 (0) 1432 264264  
vehicelifetimesolutions.schaeffler.com

SCHAEFFLER  
REXP